DART AEROSPACE LTD	Work Order:	24612
Description: Return 422	Part Number:	D2668-1/D2667-1
Dwg:	Qty:	1
		Page of

Step	Location	Procedure	By	Date	Qty
1	DC	Issue Traveler			
1	QC5.3	Inspect saddles D2668-1 B7350 and D2667-1 B7348 for damage.		05.10.19	1
2	FP	clean saddle holes ~~without~~ free of powder coat without changing hole dimensions as per Dwg's, and Alodine holes.		05 10 26	1
3	FP	re-powder coat as per RS1004, following QS1 005 4,3		05 10 27	1
4	QC3	Inspect Powder coat.	CZ	05/10/27	1
5	St.	wrap in foam, and identify with original batch numbers due to original batch is engraved into the saddles, and stock		05/10/27	1 CZ
6	AC	COST: 2070	SAC	05-10-28	1
7	QC/QC21	Close w/o.		05/10/28	1

Rev	Date	Change	Revised By	Approved